









X 15 mins



<p>A</p>  <p>x1</p>	<p>N</p>  <p>x1</p>	<p>B</p>  <p>x1</p>
<p>J</p>  <p>x1</p>	<p>C</p>  <p>x1</p> <p>E</p>  <p>x1</p> <p>D</p>  <p>x1</p>	<p>F</p>  <p>x1</p>
<p>G</p>  <p>M6*18</p> <p>x12</p>	<p>P</p>  <p>M6*25</p> <p>x8</p>	<p>K</p>  <p>M6*45</p> <p>x4</p>
<p>L</p>  <p>x4</p>	<p>H</p>  <p>x28</p>	<p>I</p>  <p>x1</p>
<p>M</p>  <p>x1</p>	<p>R</p>  <p>M6</p> <p>x20</p>	



EN Do not fully tighten the bolts until all parts are in place.

ET Pingutage kruvid lõplikult alles siis, kui kõik detailid on oma kohal.

FI Kiristä ruuvit vasta, kun kaikki osat ovat kohdallaan.

LV Skrūves kārtīgi pievelciet tikai pēc visu detaļu uzstādīšanas.

SV Dra inte åt skruvarna förrän alla delar är på plats.

LT Varžtai galutinai užveržiami tik sumontavus visas detales.


DK Stram ikke boltene helt, før alle dele er samlet.

DE Ziehen Sie die Schrauben erst vollständig fest, wenn alle Teile montiert sind.


NO Ikke stram boltene helt før alle deler er på plass.

PL Nie dokręcać całkowicie śrub, dopóki wszystkie elementy nie znajdą się na swoich miejscach.


1




2




3



4



5



6

