





2

A circular progress indicator showing 80% completion, with a curved arrow indicating the direction of assembly.

3

A circular progress indicator showing 100% completion, with a curved arrow indicating the direction of assembly.

4

