

ASSEMBLY INSTRUCTION MC15-BY



A



4PCS

B



4PCS

C



1PC




①




X 1

Tightening the screws
in clockwise direction




①

②



X 1



②

