



ASSEMBLY INSTRUCTION

HARDWARE LIST			
NO.	PART		Q' TY
A		frame	4
B		metal connection	2
C		glass top	1
D		screw	4
E		metal gasket	4
F		screw nut	4
G		rod	4
H		hexagon spanner	1
J		Allen key	2



step 1

step 2



step 3

step 4

