




veke

INSTRUCTION




A

x1




B

x1




C

x1



D

x4



M6x15

K

x8



L


x8




M

x1


STEP1:







STEP2:





STEP3:




							
E		x2		F		x2	
D		x8		K		x16	
		M6x15		L		x16	


STEP4:


STEP5:




STEP6:




STEP7:




	H	x1	I	x1	J	x1
	D	x4	K	x8	L	x8
		M6x15				



STEP9:



STEP10:



STEP11:

